

Riviera Pond Maintenance

Before After



The 'Before' image shows a dry, overgrown area with tall, brown grasses and a concrete structure partially visible. The 'After' image shows the same area after maintenance, featuring a clear, winding stream with a rocky bed, green grass, and a concrete structure in the foreground.

Riviera Pond Maintenance

Outfall Channel Before Outfall Channel After



The 'Outfall Channel Before' image shows a narrow, overgrown channel with a concrete curb and a metal railing, surrounded by dry grass and residential buildings. The 'Outfall Channel After' image shows the same channel after maintenance, with a wider, clearer water flow, a concrete curb, and a metal railing, surrounded by green grass and residential buildings.

Other System Maintenance

TV CREW at Work



Inside TV Van



Other Maintenance Activity

Inlet/Vault Cleaning



Quebec Pond Final

